https://www.newriverrenewal.co.uk/

Following Meeting with TW held October 4th at 11am Coalhouse Café – Woodberry Wetlands

ACTION LOG & PROGRESS REPORT - 28-10-2022

PRIORITY AREA	ACTION	Progress	Response from TW + LBH
1) Restoration of the	Path from SSR to Finsbury Park is	Thames Water has raised an	On the site access point - I
New River path to	expected to be renewed before	order with their contractor for the	picked this up with James
reduce the risk of falls	Christmas 2022.	relaying of the path to Finsbury	last week and am following
and enable access for all		Park, and TW are working with	up with the relevant people
in compliance with the	Councillors were asked: Would it	LBH to achieve an agreement to	in Hackney. Caroline
Equality Act 2010.	be possible for you to speed up	place a temporary compound on	
	the process with the London	the adjacent site, as this is	
This is particularly	Borough of Hackney.	needed to allow safe access to	
relevant to the section		the site to carry out the work,	
from SSR to FP but is		and allow access for delivery of	
relevant to most other		materials.	
sections.		If LBH can get this matter	
		sorted, work could begin to	
		renew the path in the near	
		future. Hopefully completed	
		before Christmas.	
		The type of meterial yeard is yet	
		The type of material used is yet	
		to be decided, but will be environmentally friendly. The	
		TW Water Quality team will	
		decide on the material used.	
		decide on the material used.	

2) Dangerous section of the path – especially following rain.	Campaign review, photos and assessment planned for November 7 th at 3pm. Emphasis on compliance with Equality Act and Duty of Care by LBH and TW. <u>Duty of Care</u> which may require actions be taken to protect users of the paths, plus the installation of signage regarding potential hazards.	Apart from proposals for SSR to Finsbury Park, no action since gravelling of the path. It is a long term problem caused by lack of any response mechanism when paths become dangerous for walkers.	No action from LBH or TW
3) Ownership of section of the River and Bank	Map requested from Councillors and James showing who owns each section and responsibility and accountability.	Caroline has provided map showing ownership of each area.	Complete
4) Better communications between all parties needed so that potential hazards can be reported quickly and responded without delay.	Discussed with James but apart from his meetings with Councillors no action. System is required, so that reports of precarious or dangerous paths and rubbish can easily be dealt with through a clear reporting line, and passed to the agency best suited to remove the rubbish or secure the safety of the path. Effective collaboration between the relevant bodies is important and James confirmed this process	On coordination more broadly Cllrs spoke to the relevant LBH Council Heads of Service and am linking him in with James TW	No progress with regard to actions to resolve the problem of routine reporting and accountability for hazards and repair of hazardous sections.

	is in the early stages of development.		
5) Identify which parts of the New River are contaminated and require regular removal of rubbish to maintain and restore the natural wildlife environment.	The cafe could be the place walkers report anything of note, e.g. contamination of the NR. The mobile number of whoever is on duty on any particular day and other contact details should be available on a board near the cafe or front entrance. Also posters in the café and on the path advising walkers how to report contamination of NR.	Rubbish collection from the NR only takes place when there is heavy contamination, and this is carried out by the LWT, and only on the section adjacent to the East Reservoir.	
	James agreed to share a copy of the current agreement between Thames Water and the London Wildlife Trust	No document received We would like a copy of any agreement between TW/LWT regarding activities carried	
	We proposed a service level agreement be established between LWT and TW, so that LWT can be paid to regularly check the river (e.g. every two weeks), remove rubbish, and clear rubbish from the proposed	out by LWT on behalf of TW.	
6) Current	Gauge House grill. The river beneath Lordship Road	No progress. James reports that	Cllrs will pick up with
contamination –	is heavily contaminated, despite	he is waiting for the LBH to give	James re who he /TW
very slow response	this issue being raised several	consent for divers to enter the	have been speaking to re

7) Risks to volunteers removing larger items from the NR	times over the past months with TW and Cllrs. There is no quick response mechanism at the moment. The rubbish under Lordship Road has been left for months. Rubbish was removed nearby but the rubbish under the bridge left despite several requests to TW and reporting to our Cllrs. We agreed to consider the risk to volunteers of removing heavy items from the river, and the importance of these activities being undertaken by experts, who would not be at risk of harm. We agreed that legal advice was needed in relation to role of volunteers in cleaning up the river.	NR by Lordship Road, clean the valve and the river. Broken glass and trolley that remained on the SSR path for two years have now been removed. Mattress still not removed from near Newton Close. Other items of junk not removed, e.g. cones and wooden boards. We have not received a progress report from TW.	Clearance of the river under Lordship Road No Action
8) Quality of Water in the East Reservoir	Water from East Reservoir is pumped to Walthamstow and after cleansing is used as drinking water	We asked James for a copy of the recent water quality reports.	No action
9) Need for responsibility for maintenance of each	Part of discussion between Councillors and James. LBH actively looks after path from	No progress Action needed from Hackney Council re rubbish bins and	No action
section of the path to be accepted by Thames	large children's playground to Lordship Road.	regular emptying of bins.	

Weter and LDU	Mana mulabiah biga ana magail an tha	No action describe of motile forces	
Water and LBH.	More rubbish bins are need on the	No action cleaning of path from	
Currently, little evidence	west side of Lordship Road and by	Newton Close to FP except from	
of coordinated	Newnton Close. Lots of rubbish is	volunteers.	
arrangements between	accumulating by the Newnton		
responsible bodies for	Close bridge. Contaminated paths		
effective maintenance.	soon contaminate the NR.		
	Regular picking by Berkley Homes		
	worker and volunteers is going		
	well on the west side of Lordship		
	Road.		
	The next volunteer path 'clean up'		
	by volunteers on Wednesday		
	2nd November at 9.30am (meeting		
	at Park View Cafe).		
10) Japanese Knotweed	Raised with James and LBH	The Council will not take	No action
is growing on a few	rtaissa miir sames ana 2211	responsibility for its removal	
section of the path by		even though they employ a JKW	
the football pitch on		expert. Thames Water has	
Thames Water land.		taken no action	
Thanks Water land.		We recommend that TW pays	
		LBH or LWT to control grown	
		of JKW	
11) We propose a grill be	No Action		No action
	NO ACION	No progress	NO action
placed on the Gauge House near Newnton			
Close, to stop rubbish			
flowing down to the			
reeds where birds nest.			

			[
12) Appropriate	We have asked for each of the	Nothing in writing yet. Some	No Action
accountability for path	four bodies that have	signs of progress, for example:	
and river to	accountability for the river and	TW's SSR to FP path plan.	
develop wildlife areas	path to be clear about their		
and create an	responsibilities, and respond	Competence of LWT in relation	
environment that is safe	appropriately when issues are	to ad hoc clearing of river junk	
for the enjoyment of	raised. LBH, TW, LWT,	needs to be recognised and	
residents and visitors	Better.Com.	funded. Rapid reporting and	
	A proactive approach is required,	rapid action is required to	
	not just responding when the birds	protect wildlife.	
	are nesting in plastic.	•	
	Memorandum of understanding		
	is required so that the		
	responsibilities of each body		
	become transparent.		
13) Communications	Bulletin boards are needed to	See also item 5	NO Action
with local residents	share with local people the best		
	ways of reporting contamination of		
	the river and path, and hazardous		
	events on the path, e.g. deep mud		
	after heavy rain. We agreed a		
	coherent strategy is needed that		
	ensures paths are safe throughout		
	the whole year and contamination		
	of the river and path substantially		
	reduced. Rapid action to deal with		
	deep muddy sections of the path		
	and identified persons who can		
	take rapid action.		

14) Sterile River – Castle to Lordship Road	Part of the New River west from the Castle to Lordship Road is sterile. This is because of the dye put in the water by Better.com. The dye kills riverbottom plants and is supposed to make the West Reservoir safer for swimmers and boaters. We are concerned about the impact on fish and other wildlife. We did discuss with Better.Com whether the dye could be put in at another location where it would impact less heavily on wildlife, but they said this would make no difference. They claim that the dye does not harm fish, but there have been a number of dead fish in west end of the river over the summer.	We have asked for an expert from LWT advise us on whether changes can be made to the policy and practice of adding dye to the river and what action can be taken to bring the west river back to life. Response awaited from LWT. Does TW have experts who can provide advice on this issue?	LWT suggest referral to the EA. They will seek advice from their Conservation Team.
15) Public Meeting about the New River	James has agreed to speak at a public meeting about development in the New River	Date and location to be agreed. Probably at Redmond Centre.	